

**Federal Aviation
Administration**

Transmittal Letter 18-22

September 7, 2018

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBE	FDC DATE	SUBJECT
11-Oct-18	MN	Willmar	Willmar Muni-John L Rice Field	8/7162	8/31/18	VOR RWY 31, Orig-A

AIRAC Date: 11 OCTOBER 2018

**FDC 8/7162 BDH IAP WILLMAR MUNI-JOHN L RICE FIELD, Willmar, MN. VOR RWY
31, ORIG-A... CHART NOTE: CIRCLING RWY 3, 21 NA. THIS IS VOR RWY 31,
ORIG-B. 1808241851-PERM**