

PREPARED BY THE PRODUCT SUPPORT GROUP, AJV-34

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

| AIRAC DATE | STATE | CITY | AIRPORT | FDC NUMBER | FDC DATE | SUBJECT |
|---------------|-------|---------|---------------------------------------|---------------|----------|-----------------------|
| 8/22/13 | AK | Atqasuk | Atqasuk Edward Burnell Sr Memorial | 2/7242 | 7/16/13 | NDB RWY 24, Amdt 2 |

FDC **2/7242** ATK FI/P IAP ATQASUK EDWARD BURNELL SR
MEMORIAL, ATQASUK, AK. NDB RWY 24, AMDT 2... CHANGE FAC TO
253. CHANGE PT TO 073 OUTBOUND. CHANGE TERMINAL ROUTE
MEADE INT TO ATK NDB TO 139. CHANGE MISSED APPROACH
HOLDING TO HOLD E, RT, 253 INBOUND. THIS IS NDB RWY 24, AMDT
2A.