

PREPARED BY THE PRODUCT SUPPORT GROUP, AJV-34

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
11/14/13	CA	San Jose	Norman Y. Mineta San Jose Intl	3/0757	9/18/13	RNAV (GPS) RWY 29, Orig-C

FDC **3/0757** SJC FI/P IAP NORMAN Y. MINETA SAN JOSE INTL, SAN JOSE, CA. RNAV (GPS) RWY 29, ORIG-C... CHART NOTE: RWY 29 STRAIGHT-IN AND CIRCLING MINIMUMS NA AT NIGHT. CHART NOTE: HELICOPTER VISIBILITY REDUCTION BELOW 1SM NOT AUTHORIZED. DELETE VDP. 34:1 IS NOT CLEAR. CHART PLANVIEW NOTE: PROCEDURE NA FOR ARRIVALS AT LICKE ON V485 SOUTHEAST BOUND. THIS IS RNAV (GPS) RWY 29, ORIG-D.