

**Federal Aviation
Administration**

Transmittal Letter 15-13

MAY 8, 2015

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DAT	SUBJECT
25-Jun-15	IL	Chicago/West Chicago	Dupage	5/6879	04/21/15	VOR RWY 2L, AMDT 1A

AIRAC Date: 25 JUNE 2015

FDC 5/6879 DPA IAP DUPAGE, CHICAGO/WEST CHICAGO, IL. VOR RWY 2L, AMDT 1A... S-2L HAT 746 ALL CATS. OCADI FIX MINIMUMS: S-2L HAT 666 ALL CATS. CHART TDZE 754 DELETE THRE 751. THIS IS VOR RWY 2L, AMDT 1B.
1504141232-PERM