

PREPARED BY THE PRODUCT SUPPORT GROUP, AJV 34

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
18-Sep-14	CT	Windsor Locks	Bradley Intl	4/4238	08/08/14	ILS OR LOC RWY 6, ILS RWY 6 (SA CAT I), ILS RWY 6 (CAT II & III), Amdt 37

AIRAC Date: 18 SEP 2014

FDC **4/4238** BDL IAP BRADLEY INTL, WINDSOR LOCKS, CT. ILS OR LOC RWY 6
 AMDT 37... ILS RWY 6 (SA CAT I) AMDT 37... ILS RWY 6 (CAT II & III) AMDT 37...
 CHANGE THRE 173 TO TDZE 173. THIS IS ILS OR LOC RWY 6 AMDT 37A, ILS
 RWY 6 (SA CAT I) AMDT 37A, ILS RWY 6 (CAT II & III) AMDT 37A. 1404161500-
 PERM