

PREPARED BY THE PRODUCT SUPPORT GROUP, AJV-34

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
9/19/13	VA	Warrenton	Warrenton-Fauquier	3/0309	8/7/13	VOR RWY 15, Amdt 4A

FDC **3/0309** HWY FI/P IAP WARRENTON-FAUQUIER, WARRENTON, VA. VOR RWY 15, AMDT 4A... S-15 HATH 747 ALL CATS. VIS CAT B 1 1/4. CIRCLING HAA 724 ALL CATS. MABEE FIX MINIMUMS S-15 MDA 820/HATH 507 ALL CATS. VIS CATS C/D 1 3/8. MABEE FIX MINIMUMS CIRCLING MDA 820/HAA 484 CATS A/B/C, HAA CAT D 564. DELETE NOTES. CHART NOTE: WHEN LOCAL ALTIMETER SETTING NOT RECEIVED, USE CULPEPER ALTIMETER SETTING AND INCREASE ALL MDA 40 FEET; INCREASE S-15 CATS C/D AND CIRCLING CATS C/D VISIBILITY 1/2 MILE; INCREASE MABEE FIX MINIMUMS S-15 CATS C/D AND CIRCLING CAT C VISIBILITY 1/4 MILE. CHART NOTE: HELICOPTER VISIBILITY REDUCTION BELOW 3/4 SM NOT AUTHORIZED. CHANGE MISSED APPROACH TO READ: CLIMBING RIGHT TURN TO 2800 DIRECT TO CSN VORTAC AND HOLD. CHANGE TCH TO READ: 52.3 DELETE PROFILE NOTE: VGSI AND DESCENT ANGLES NOT COINCIDENT. DELETE TDZE. CHART THRE 313 CHART APT ELEV 336 CHART FAS OBST: 563 TREE 383645N/0774555W. THIS IS VOR RWY 15, AMDT 4B.