

PREPARED BY THE PRODUCT SUPPORT GROUP, AJV 34

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
13-Nov-14	AL	Bessemer	Bessemer	4/8100	09/29/14	RNAV (GPS) RWY 23, Orig

AIRAC Date: 13 NOVEMBER 2014

FDC **4/8100** EKY IAP BESSEMER, BESSEMER, AL. RNAV (GPS) RWY 23, ORIG...
DELETE PROFILE NOTE: VGSI AND RNAV GLIDEPATH NOT COINCIDENT.
CHANGE HELICOPTER NOTE TO READ: HELICOPTER VISIBILITY REDUCTION
BELOW 3/4 SM NOT AUTHORIZED. CHANGE FOR UNCOMPENSATED BARO-VNAV
SYSTEMS NOTE TO READ: FOR UNCOMPENSATED BARO-VNAV SYSTEMS,
LNAV/VNAV NA BELOW -16C (4) OR ABOVE 54C (130F). THIS IS RNAV (GPS) RWY
23, ORIG-A. 1409221842-PERM