

PREPARED BY THE PRODUCT SUPPORT GROUP, AJV 34

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
11-Dec-14	AL	Bessemer	Bessemer	4/0030	10/23/14	ILS OR LOC RWY 5, Amdt 2

AIRAC Date: 11 DECEMBER 2014

FDC **4/0030** EKY IAP BESSEMER, BESSEMER, AL. ILS OR LOC RWY 5, AMDT 2...
DELETE PROFILE NOTE: VGSI AND ILS GLIDEPATH NOT COINCIDENT. CHART
NOTE: VDP NA WITH ALABASTER ALTIMETER SETTING. THIS IS ILS OR LOC RWY
5, AMDT 2A. 1410211327-PERM