

PREPARED BY THE PRODUCT SUPPORT GROUP, AJV 34

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
5-Feb-15	MN	New Ulm	New Ulm Muni	4/8488	12/15/14	NDB RWY 15, Amdt 2

AIRAC Date: 5 February 2015

FDC **4/8488** ULM IAP NEW ULM MUNI, NEW ULM, MN. NDB RWY 15, AMDT 2... S-15 HAT 589 ALL CATS. ECUJU FIX MINIMUMS (DME REQUIRED): S-15 HAT 409 ALL CATS. DELETE NOTE: RWY 15 STRAIGHT-IN AND CIRCLING MINIMUMS NA AT NIGHT. CHART TDZE 1011. DELETE THRE 1005. CHART PROFILE NOTE: VGSI AND DESCENT ANGLES NOT COINCIDENT.. THIS IS NDB RWY 15, AMDT 2A.
 1412121423-PERM