

PREPARED BY THE PRODUCT SUPPORT GROUP, AJV 34

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
5-Feb-15	MN	New Ulm	New Ulm Muni	4/8490	12/15/14	NDB RWY 33, Amdt 2

AIRAC Date: 5 February 2015

FDC 4/8490 ULM IAP NEW ULM MUNI, NEW ULM, MN. NDB RWY 33, AMDT 2... S-33 HAT 789 ALL CATS. ECUZU FIX MINIMUMS (DME REQUIRED): S-33 HAT 609 ALL CATS. CHART TDZE 1011. DELETE THRE 1004.. THIS IS NDB RWY 33, AMDT 2A. 1412121423-PERM