

U.S. Department
of Transportation

800 Independence Ave., S.W
Washington, D.C. 20591

**Federal Aviation
Administration**

Transmittal Letter 15-08

February 27, 2015

**PREPARED BY THE PRODUCT SUPPORT GROUP, AJV-34
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
2-Apr-15	KY	Springfield	Lebanon-Springfield	5/8168	02/12/15	RNAV (GPS) RWY 29, Orig-B

FDC **5/8168** 6I2 IAP LEBANON-SPRINGFIELD, SPRINGFIELD, KY. RNAV (GPS) RWY 29, ORIG-B... DELETE NOTE: RWY 29 STRAIGHT-IN AND CIRCLING MINIMUMS NA AT NIGHT. DELETE NOTE: HELICOPTER VISIBILITY REDUCTION BELOW 1SM NA. CHART NOTE: HELICOPTER VISIBILITY REDUCTION BELOW 3/4 SM NOT AUTHORIZED. CHART VDP AT 1.49 NM TO RW 29. CHART NOTE: VDP NA WITH DANVILLE ALTIMETER SETTING.

THIS IS RNAV (GPS) RWY 29 ORIG-C. 1501311427-PERM