

U.S. Department
of Transportation

800 Independence Ave., S.W
Washington, D.C. 20591

**Federal Aviation
Administration**

Transmittal Letter 15-08

February 27, 2015

**PREPARED BY THE PRODUCT SUPPORT GROUP, AJV-34
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME,
LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
2-Apr-15	TX	Sulphur Springs	Sulphur Springs Muni	5/9522	02/12/15	RNAV (GPS) RWY 19, Orig

**FDC 5/9522 SLR IAP SULPHUR SPRINGS MUNI, SULPHUR SPRINGS, TX.
RNAV (GPS) RWY 19, ORIG... LPV DA 676 LNAV/VNAV DA 776 LNAV HAT 364
CHART TDZE 476 DELETE THRE 466.**

THIS IS RNAV (GPS) RWY 19, ORIG-A. 1502050015-PERM