

U.S. Department
of Transportation

800 Independence Ave., S.W
Washington, D.C. 20591

**Federal Aviation
Administration**

Transmittal Letter 15-08

February 27, 2015

**PREPARED BY THE PRODUCT SUPPORT GROUP, AJV-34
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
2-Apr-15	WI	Marshfield	Marshfield Muni	5/9569	02/11/15	RNAV (GPS) RWY 23, Orig

FDC 5/9569 MFI IAP MARSHFIELD MUNI, MARSHFIELD, WI. RNAV (GPS) RWY 23, ORIG... LP HAT 382 ALL CATS. LNAV HAT 402 ALL CATS. CHART TDZE 1258. DELETE THRE 1249.

THIS IS RNAV (GPS) RWY 23 ORIG-A. 1502050107-PERM