

PREPARED BY THE PRODUCT SUPPORT GROUP, AJV-53

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
EFFECTIVE UPON PUBLICATION

| AIRAC DATE | STATE | CITY | AIRPORT | FDC NUMBER | FDC DATE | SUBJECT |
|---------------|-------|------------------------|----------------------------|---------------|-------------|------------------------|
| 28-May-15 | FL | Sarasota/ Bradenton | Sarasota/Bradenton Intl | 5/2004 | 04/14/15 | VOR RWY 14, Amdt 18 |

AIRAC Date: 28 MAY 2015

FDC **5/2004** SRQ IAP SARASOTA/BRADENTON INTL, SARASOTA/BRADENTON, FL. VOR RWY 14, AMDT 18... CHANGE THRE 23 TO TDZE 23. DELETE NOTE: WHEN VGSI INOPERATIVE, CIRCLING RWY 4/22 NA AT NIGHT. CHART NOTE: NIGHT LANDING: RWY 4, 22 NA. THIS IS VOR RWY 14, AMDT 18A. 1504021939-PERM