

U.S. Department  
of Transportation

800 Independence Ave., S.W.  
Washington, D.C. 20591

**Federal Aviation  
Administration**

**Transmittal Letter 15-17**

**July 2, 2015**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME,  
LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
20-Aug-15	NY	Schenectady	Schenectady County	5/3221	06/24/15	RNAV (GPS) RWY 22, Orig-A

**EFFECTIVE 20 AUGUST 2015**

**FDC 5/3221 SCH IAP SCHENECTADY COUNTY, SCHENECTADY, NY. RNAV  
(GPS) RWY 22, ORIG-A... CHANGE HELICOPTER VISIBILITY REDUCTION  
NOTE TO READ: HELICOPTER VISIBILITY REDUCTION BELOW 3/4 SM NOT  
AUTHORIZED. CHANGE TDZE 378 TO THRE 378. THIS IS RNAV (GPS) RWY  
22 ORIG-B. 1505191124-PERM**