

U.S. Department
of Transportation

800 Independence Ave., S.W.
Washington, D.C. 20591

**Federal Aviation
Administration**

Transmittal Letter 15-08

February 27, 2015

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
2-Apr-15	WI	Mosinee	Central Wisconsin	5/9560	02/11/15	ILS OR LOC RWY 35, Amdt 2

**FDC 5/9560 CWA IAP CENTRAL WISCONSIN, MOSINEE, WI. ILS OR LOC
RWY 35, AMDT 2... S-ILS 35 DA 1451. S-LOC 35 HAT 649 ALL CATS. HUREB
FIX MINIMUMS: S-LOC 35 HAT 329 ALL CATS. CHART TDZE 1251. DELETE
THRE 1225.**

THIS IS ILS OR LOC RWY 35, AMDT 2A. 1502050056-PERM