

**Federal Aviation  
Administration**

**Transmittal Letter 15-18**

**July 17, 2015**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
20-Aug-15	MA	Beverly	Beverly Muni	5/0583	07/06/15	RNAV (GPS) RWY 34, Orig

**Effective 20 August 2015**

**FDC 5/0583** BVY IAP BEVERLY MUNI, BEVERLY, MA. RNAV (GPS) RWY 34, ORIG... LPV DA 377. LNAV/VNAV DA 468. LNAV HAT 438 ALL CATS. CHART TDZE 102 DELETE THRE 82. DELETE NOTE: PROCEDURE NA AT NIGHT. CHART NOTE: NIGHT LANDING: RWY 9, 27, 34 NA. THIS IS RNAV (GPS) RWY 34 ORIG-A. 1507061717-PERM