

**Federal Aviation
Administration**

Transmittal Letter 10-25

October 29, 2010

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION.....						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
16-Dec-10	TX	Palacios	Palacios Muni	0/9592	10/15/10	VOR RWY 13, Amdt 10B

AIRAC Date: 16 December 2010

FDC **0/9391** PSX FI/P PALACIOS MUNI, PALACIOS, TX. VOR RWY 13, AMDT 10B... MSA FROM PSX VORTAC 070 TO 160 16,000, 160 TO 070 2600. ADD NOTE: VISIBILITY REDUCTION BY HELICOPTERS NA.

THIS IS VOR RWY 13, AMDT 10C.