

**Federal Aviation
Administration**

Transmittal Letter 15-21

August 28, 2015

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
15-Oct-15	CA	Palo Alto	Palo Alto Arpt Of Santa Clara Co	5/2424	08/17/15	Takeoff Minimums and (Obstacle) DP, Orig-A

AIRAC Date: 15 October 2015

FDC 5/2424 PAO ODP PALO ALTO ARPT OF SANTA CLARA CO, PALO ALTO, CA.
TAKEOFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES ORIG-A...
CHANGE AIRPORT NAME TO READ: PALO ALTO. THIS IS TAKEOFF MINIMUMS
AND (OBSTACLE) DEPARTURE PROCEDURES, ORIG-B. 1508131903-PERM