

U.S. Department
of Transportation

800 Independence Ave., S.W.
Washington, D.C. 20591

**Federal Aviation
Administration**

Transmittal Letter 16-05

January 15, 2016

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME,
LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
3-Mar-16	MA	Beverly	Beverly Muni	5/2052	12/29/15	LOC RWY 16, Amdt 7A

EFFECTIVE 3 MARCH 2016

**FDC 5/2052 BVY IAP BEVERLY MUNI, BEVERLY, MA. LOC RWY 16, AMDT
7A... S-16 CAT C/D VIS 1 3/8. DELETE NOTE: NIGHT LANDING: RWY 9, 27, 34
NA. CHART NOTE: NIGHT LANDING: RWY 9, 27 NA. CHANGE LOCAL
ALTIMETER SETTING NOTE TO READ: WHEN LOCAL ALTIMETER SETTING
NOT RECEIVED, USE LAWRENCE ALTIMETER SETTING AND INCREASE
ALL MDA 40 FEET. THIS IS LOC RWY 16, AMDT 7B. 1512041821-PERM**