

**Federal Aviation
Administration**

Transmittal Letter 12-12

APRIL 27, 2012

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DAT	SUBJECT
31-May-12	MT	Billings	Billings Logan Intl	2/1298	4/20/12	VOR/DME RWY 28R, AMDT 14

AIRAC Date: 31 MAY 2012

FDC 2/1298 BIL FI/P IAP BILLINGS LOGAN INTL, BILLINGS, MT. VOR/DME RWY 28R, AMDT 14... PT LEFT SIDE OF COURSE 082.00 OUTBOUND 5700 FT WITHIN 10 MILES OF MUSTY (IAF). THIS IS VOR/DME RWY 28R, AMDT 14A.