

U.S. Department
of Transportation

800 Independence Ave., S.W.
Washington, D.C. 20591

**Federal Aviation
Administration**

Transmittal Letter 16-08

February 26, 2016

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME,
LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
31-Mar-16	CO	Meeker	Meeker Coulter Fld	6/5331	02/11/16	VOR-A, Amdt 1

EFFECTIVE 31 MARCH 2016

**FDC 6/5331 EEO IAP MEEKER COULTER FLD, MEEKER, CO. VOR-A, AMDT
1... CHART NOTE: NIGHT LANDING: RWY 21 NA. CHART NOTE:
HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NA. THIS IS VOR-A,
AMDT 1A. 1601210504-PERM**