

**Federal Aviation  
Administration**

**Transmittal Letter 16-11**

**April 8, 2016**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows: .....EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DAT	SUBJECT
26-May-16	IN	Marion	Marion Muni	6/7312	03/23/16	RNAV (GPS) RWY 33, Orig-B

**AIRAC Date: 26 MAY 2016**

FDC 6/7312 MZZ IAP MARION MUNI, MARION, IN. RNAV (GPS) RWY 33, ORIG-B...  
DELETE NOTE: RWY 33 STRAIGHT-IN AND CIRCLING AND CIRCLING TO RWY 15  
NA AT NIGHT. CHART NOTE: NIGHT LANDING: RWY 15 NA. CHART VDP AT 1.12  
MILES TO RW33. CHANGE PLANVIEW PROCEDURE NA NOTE TO READ:  
PROCEDURE NA FOR ARRIVALS AT PENDS ON V14-192-210 SOUTHWEST  
BOUND, AND ARRIVALS AT HAROD ON V221 NORTHEAST BOUND. THIS IS  
RNAV (GPS) RWY 33, ORIG-C. 1603181451-PERM