

**Federal Aviation
Administration**

Transmittal Letter 16-18

July 15, 2016

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME,
LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DAT	SUBJECT
18-Aug-16	ND	Mandan	Mandan Muni	6/6648	7/7/16	VOR-A, Amdt 2

AIRAC Date: 18 AUGUST 2016

FDC 6/6648 Y19 IAP MANDAN MUNI, MANDAN, ND. VOR-A, AMDT 2... CHART NOTE:
CIRCLING TO RWYS 4 AND 22 NA. THIS IS VOR-A, AMDT 2A. 1605191308-PERM