

**Federal Aviation
Administration**

Transmittal Letter 10-07

February 19, 2010

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DAT	SUBJECT
8-Apr-10	IA	Storm Lake	Storm Lake Muni	0/3485	2/4/10	RNAV (GPS) RWY 17, ORIG

AIRAC Date: 8 APRIL 2010

FDC 0/3485 SLB FI/P STORM LAKE MUNI, STORM LAKE, IA. RNAV (GPS) RWY 17, ORIG... DELETE NOTE: STRAIGHT-IN MINIMUMS NA AT NIGHT. DELETE NOTE: CIRCLING TO RWYS 17, 6, 31, 24 AND 13 NA AT NIGHT. THIS IS RNAV (GPS) RWY 17, ORIG-A..