

U.S. Department  
of Transportation

800 Independence Ave., S.W.  
Washington, D.C. 20591

**Federal Aviation  
Administration**

**Transmittal Letter 17-12**

**April 21, 2017**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

| AIRAC<br>DATE | STATE | CITY         | AIRPORT      | FDC<br>NUMBER | FDC<br>DATE | SUBJECT                      |
|---------------|-------|--------------|--------------|---------------|-------------|------------------------------|
| 25-May-17     | MS    | Olive Branch | Olive Branch | 7/7393        | 4/5/17      | RNAV (GPS) RWY<br>36, Amdt 1 |

**AIRAC Date: 25 MAY 2017**

**FDC 7/7393** OLV IAP OLIVE BRANCH, OLIVE BRANCH, MS. RNAV (GPS) RWY 36, AMDT 1... CHART TDZE 401, DELETE THRE 394. LPV DA 709. LNAV/VNAV DA 915. LNAV HAT 599 ALL CATS. CHART NOTE: RWY 36 HELICOPTER VISIBILITY REDUCTION BELOW 3/4 SM NOT AUTHORIZED. DELETE NOTE: HELICOPTER VISIBILITY REDUCTION BELOW 3/4 SM NOT AUTHORIZED. THIS IS RNAV (GPS) RWY 36, AMDT 1A. 1702231838-PERM