

U.S. Department  
of Transportation

800 Independence Ave., S.W.  
Washington, D.C. 20591

**Federal Aviation  
Administration**

**Transmittal Letter 17-13**

**May 5, 2017**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
22-Jun-17	NY	Niagara Falls	Niagara Falls Intl	7/3774	4/28/17	TACAN RWY 28R, Orig

**AIRAC Date: 22 JUNE 2017**

FDC **7/3774** IAG IAP NIAGARA FALLS INTL, NIAGARA FALLS, NY. TACAN RWY 28R, ORIG... CHART TDZE 588, DELETE THRE 588. CHART NOTE: RWY 28R HELICOPTER VISIBILITY REDUCTION BELOW 3/4 SM NOT AUTHORIZED. CHART NOTE: RWY 6, 10R, 24, 28L HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NOT AUTHORIZED. CHART NOTE: CIRCLING RWY 6, 10R, 24, 28L NA AT NIGHT. DELETE NOTE: CIRCLING TO RWY 6/24/10R/28L NA AT NIGHT. DELETE NOTE: HELICOPTER VISIBILITY REDUCTION BELOW 3/4 SM NOT AUTHORIZED. CHART PROFILE NOTE: VGSI AND DESCENT ANGLES NOT COINCIDENT (VGSI ANGLE {2.50}/TCH {67}). THIS IS TACAN RWY 28R, ORIG-A. 1703121336-PERM