

**Federal Aviation
Administration**

Transmittal Letter 17-25

October 20, 2017

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
7-Dec-17	WY	Jackson	Jackson Hole	7/1552	10/5/17	ILS Y OR LOC RWY 19, Orig-A

AIRAC Date: 7 DECEMBER 2017

**FDC 7/1552 JAC IAP JACKSON HOLE, Jackson, WY. ILS Y OR LOC RWY 19, ORIG-
A... DELETE THRE 6451, CHART TDZE 6451. THIS IS ILS Y OR LOC RWY 19,
ORIG-B. 1708151404-PERM**