

**Federal Aviation
Administration**

Transmittal Letter 18-05

January 12, 2018

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

| AIRAC DATE | STATE | CITY | AIRPORT | FDC NUMBER | FDC DATE | SUBJECT |
|---------------|-------|----------------|----------------|---------------|-------------|----------------|
| 1-Mar-18 | OH | Upper Sandusky | Wyandot County | 7/1878 | 12/27/17 | VOR-A, Amdt 3C |

AIRAC Date: 1 MARCH 2018

FDC **7/1878** 56D IAP WYANDOT COUNTY, Upper Sandusky, OH. VOR-A, AMDT 3C...
YEVUN FIX MINIMUMS (DME REQUIRED) CIRCLING MDA 1420/HAA 590 ALL CATS.
THIS IS VOR-A, AMDT 3D. 1710241822-PERM