

**Federal Aviation
Administration**

Transmittal Letter 14-14

May 23, 2018

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

| AIRAC DATE | STATE | CITY | AIRPORT | FDC NUMBE | FDC DATE | SUBJECT |
|---------------|-------|---------|--------------|--------------|-------------|--------------------|
| 26-Jun-14 | MN | Fosston | Fosston Muni | 4/3347 | 5/7/14 | NDB RWY 34, AMDT 4 |

AIRAC Date: 6 DECEMBER 2018

FDC 4/3347 FSE IAP FOSSTON MUNI, FOSSTON, MN. NDB RWY 34, AMDT 4...
CHANGE THRE 1279 TO TDZE 1279. THIS IS NDB RWY 34, AMDT 4A. 1404031606-
PERM