

PREPARED BY THE PRODUCT SUPPORT GROUP, AJV 34

| By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION | | | | | | |
|--|-------|----------|------------------|---------------|-------------|----------------------------|
| AIRAC DATE | STATE | CITY | AIRPORT | FDC NUMBER | FDC DATE | SUBJECT |
| 11-Dec-14 | MT | Glendive | Dawson Community | 4/9443 | 10/09/14 | RNAV (GPS) RWY 30, Orig |

AIRAC Date: 11 DECEMBER 2014

FDC 4/9443 GDV IAP DAWSON COMMUNITY, GLENDIVE, MT. RNAV (GPS) RWY 30, ORIG... LPV DA 2706. LNAV/VNAV DA 2706. LNAV HAT 324 ALL CATS. CHART TDZE 2456 DELETE THRE 2454. THIS IS RNAV (GPS) RWY 30, ORIG-A.
1409251058-PERM