

**Federal Aviation
Administration**

Transmittal Letter 18-20

August 10, 2018

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBE	FDC DATE	SUBJECT
13-Sep-18	IN	Huntington	Huntington Muni	8/2780	7/27/18	VOR-A, Amdt 2

AIRAC Date: 13 SEPTEMBER 2018

FDC **8/2780** HHG IAP HUNTINGTON MUNI, Huntington, IN. VOR-A, AMDT 2...
EQUIPMENT REQUIREMENTS NOTE: DME REQUIRED. DELETE NOTE: DME
REQUIRED. DELETE PLANVIEW NOTE: DME REQUIRED. DELETE NOTE:
CIRCLING RWY 27 NA AT NIGHT. DELETE NOTE: RWY 27 HELICOPTER
VISIBILITY REDUCTION BELOW 1 SM NOT AUTHORIZED. THIS IS VOR-A, AMDT
2A. 1807242150-PERM