

U.S. Department
of Transportation

800 Independence Ave., S.W.
Washington, D.C. 20591

**Federal Aviation
Administration**

Transmittal Letter 19-01

November 16, 2018

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-54
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

| AIRAC DATE | STATE | CITY | AIRPORT | FDC NUMBER | FDC DATE | SUBJECT |
|---------------|-------|---------|--------------|---------------|-------------|-------------------------------|
| 3-Jan-19 | MN | Hallock | Hallock Muni | 8/8360 | 11/7/18 | RNAV (GPS) RWY 31, Amdt 1A |

AIRAC Date: 3 JANUARY 2019

FDC 8/8360 HCO IAP HALLOCK MUNI, Hallock, MN. RNAV (GPS) RWY 31, AMDT 1A... DELETE PROFILE NOTE: VGSI AND RNAV GLIDEPATH NOT COINCIDENT (VGSI ANGLE 3.00/TCH 28). DELETE NOTE: DME/DME RNP-0.3 NA. PBN REQUIREMENTS NOTE: RNP APCH. DELETE VDP AT 1.17 NM TO RW 31* *LNAV ONLY. CHART VDP AT 1.12 NM TO RW 31* *LNAV ONLY. THIS IS RNAV (GPS) RWY 31, AMDT 1B. 1809121334-PERM