

**Federal Aviation
Administration**

Transmittal Letter 19-13

MAY 3, 2019

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
6/20/2019	CQ	Tinian Island	Tinian Intl	9/0965	4/17/2019	NDB-A, Amdt 3

AIRAC Date: 20 JUNE 2019

FDC 9/0965 TNI IAP TINIAN INTL, Tinian Island, CQ. NDB-A, AMDT 3... CHART APT ELEV 270, DELETE APT
ELEV 271. CIRCLING HAA 790 ALL CATS. UYHEW FIX MINIMUMS**: CIRCLING CATS A/B/C MDA 1000/HAA
730, CAT D MDA 1060/HAA 790. CHART NOTE: **DME FROM I-GSN LOC/DME. THIS IS NDB-A, AMDT 3A.
1903221722-PERM