

**Federal Aviation
Administration**

Transmittal Letter 19-18

July 12, 2019

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
8/15/2019	KS	Concordia	Blosser Muni	9/0977	6/28/2019	RNAV (GPS) RWY 17, Orig-B

AIRAC Date: 15 AUGUST 2019

FDC 9/0977 CNK IAP BLOSSER MUNI, Concordia, KS. RNAV (GPS) RWY 17, ORIG-B... DELETE CIRCLING MINIMUMS. DELETE NOTE: CIRCLING RWY 35 NA AT NIGHT. DELETE NOTE: CIRCLING RWY 3, 12, 21, 30 NA. THIS IS RNAV (GPS) RWY 17, ORIG-C. 1906241546-PERM