

**Federal Aviation  
Administration**

**Transmittal Letter 19-16**

**June 14, 2019**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,  
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
7/18/2019	IL	Chicago/Lake In The Hills	Lake In The Hills	9/5212	5/30/2019	RNAV (GPS) RWY 26, Orig-A

**AIRAC Date: 18 July 2019**

FDC 9/5212 3CK IAP LAKE IN THE HILLS, Chicago/Lake In The Hills, IL. RNAV (GPS) RWY 26, ORIG-A... DELETE  
CIRCLING MINIMUMS. PBN REQUIREMENTS NOTE: RNP APCH. DELETE NOTE: DME/DME RNP-0.3 NA. THIS  
IS RNAV (GPS) RWY 26, ORIG-B. 1905291405-PERM