

**Federal Aviation
Administration**

Transmittal Letter 19-23

September 20, 2019

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
11/7/2019	OR	Mc Minnville	Mc Minnville Muni	9/5634	9/17/2019	RNAV (GPS) RWY 4, Orig-D

AIRAC Date: 7 NOVEMBER 2019

FDC 9/5634 MMV IAP MC MINNVILLE MUNI, Mc Minnville, OR. RNAV (GPS) RWY 4,
ORIG-D... DELETE CIRCLING MINIMUMS. CHART NOTE: RWY 4 HELICOPTER
VISIBILITY REDUCTION BELOW 3/4 SM NOT AUTHORIZED. DELETE NOTE: RWY
4: HELICOPTER VISIBILITY REDUCTION BELOW 3/4 SM NOT AUTHORIZED. THIS
IS RNAV (GPS) RWY 4, ORIG-E. 1909091500-PERM