

**Federal Aviation  
Administration**

**Transmittal Letter 19-16**

**June 14, 2019**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,  
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
7/18/2019	FL	Deland	Deland Muni-Sidney H Taylor Field	9/7033	6/4/2019	RNAV (GPS) RWY 5, Orig-B

**AIRAC Date: 18 July 2019**

FDC 9/7033 DED IAP DELAND MUNI-SIDNEY H TAYLOR FIELD, Deland, FL. RNAV (GPS) RWY 5, ORIG-B...  
DELETE CIRCLING MINIMUMS. THIS IS RNAV (GPS) RWY 5, ORIG-C. 1905311506-PERM