

**Federal Aviation
Administration**

Transmittal Letter 21-18

JULY 9, 2021

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
8/12/2021	AL	Huntsville	Huntsville Intl-Carl T Jones Fld	1/9959	6/25/2021	ILS OR LOC RWY 36R, Amdt 4

AIRAC Date: 12 AUGUST 2021

FDC 1/9959 HSV IAP HUNTSVILLE INTL-CARL T JONES FLD, HUNTSVILLE, AL. ILS OR LOC RWY 36R, AMDT 4... ALTERNATE MINIMUMS: ILS: STANDARD; LOC: STANDARD EXCEPT CAT E 800-2 1/4; ILS AND LOC NA WHEN LOCAL WEATHER NOT AVAILABLE. THIS IS ILS OR LOC RWY 36R, AMDT 4A. 2105210300-PERM