

**Federal Aviation
Administration**

Transmittal Letter 18-26

November 2, 2018

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBE	FDC DATE	SUBJECT
6-Dec-18	NY	Albany	Albany Intl	8/3214	10/29/18	VOR RWY 28, Orig-C

AIRAC Date: 6 DECEMBER 2018

FDC **8/3214** ALB IAP ALBANY INTL, Albany, NY. VOR RWY 28, ORIG-C... CHART
NOTE: STRAIGHT-IN RWY 28 NA AT NIGHT, CIRCLING RWY 28 NA AT NIGHT.
CHART NOTE: RWY 28 HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NOT
AUTHORIZED. EQUIPMENT REQUIREMENTS NOTE: DME OR RADAR REQUIRED.
DELETE NOTE: DME OR RADAR REQUIRED. THIS IS VOR RWY 28, ORIG-D.
1810261931-PERM