

**Federal Aviation  
Administration**

**Transmittal Letter 21-23**

**September 17, 2021**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows: .....EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
11/4/2021	RI	Newport	Newport State	1/6899	9/1/2021	LOC RWY 22, Amdt 7E

**AIRAC Date: 4 NOVEMBER 2021**

FDC 1/6899 UUU IAP NEWPORT STATE, NEWPORT, RI. LOC RWY 22, AMDT 7E... CIRCLING CAT C MDA 780/HAA 608, CAT C VIS 1 3/4. DAAME FIX MINIMUMS: CIRCLING CAT C MDA 780/HAA 608, CAT C VIS 1 3/4. THIS IS LOC RWY 22, AMDT 7F. 2108271306-PERM