

**Federal Aviation  
Administration**

**Transmittal Letter 20-18**

**July 10, 2020**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows: .....EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
8/13/2020	NE	Aurora	Aurora Muni - Al Potter Field	0/3125	6/25/2020	RNAV (GPS) RWY 34, Orig

**AIRAC Date: 13 AUGUST 2020**

FDC 0/3125 AUH IAP AURORA MUNI - AL POTTER FIELD, AURORA, NE. RNAV (GPS) RWY 34, ORIG... CHART CIRCLING ICON. THIS IS RNAV (GPS) RWY 34, ORIG-A. 2006251838-PERM