

U.S. Department
of Transportation

800 Independence Ave., S.W.
Washington, D.C. 20591

**Federal Aviation
Administration**

Transmittal Letter 16-08

February 26, 2016

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME,
LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
31-Mar-16	TN	Jackson	Mc Kellar-Sipes Rgnl	5/6906	02/11/16	RNAV (GPS) RWY 20, Orig

EFFECTIVE 31 MARCH 2016

FDC **5/6906** MKL IAP MC KELLAR-SIPES RGNL, JACKSON, TN. RNAV (GPS)
RWY 20, ORIG... CHART NOTE: NIGHT LANDING: RWY 29 NA. CHANGE
HELICOPTER VISIBILITY REDUCTION NOTE TO READ: HELICOPTER
VISIBILITY REDUCTION BELOW 3/4 SM NOT AUTHORIZED. THIS IS RNAV
(GPS) RWY 20, ORIG-A. 1512142101-PERM