

**Federal Aviation
Administration**

Transmittal Letter 09-17

JULY 10, 2009

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DAT	SUBJECT
06/26/09	CT	Groton/New London	Groton-New London	9/5844		RNAV (GPS) RWY 23, Orig

AIRAC Date: 26 JUNE 2009

FDC 9/5844 GON FI/P GROTON-NEW LONDON, GROTON/NEW LONDON, CT.
RNAV (GPS) RWY 23, ORIG...CHANGE ALL REFERENCE TO FIX ZEMAP TO
BRRET. THIS IS RNAV (GPS) RWY 23, ORIG-A.