

**Federal Aviation
Administration**

Transmittal Letter 20-03

December 13, 2019

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

| AIRAC DATE | STATE | CITY | AIRPORT | FDC NUMBER | FDC DATE | SUBJECT |
|------------|-------|----------|----------------------------------|------------|------------|-------------------------------|
| 1/30/2020 | KS | Goodland | Renner Fld /Goodland Muni/ | 9/5498 | 11/21/2019 | RNAV (GPS) RWY 30, Amdt 1B |

AIRAC Date: 30 JANUARY 2020

FDC 9/5498 GLD IAP RENNER FLD /GOODLAND MUNI/, Goodland, KS. RNAV (GPS) RWY 30, AMDT 1B... CIRCLING MDA CAT D 4240/HAA 583. CHART CIRCLING ICON. DELETE NOTE CIRCLING NA SOUTH OF RWY 5-30. CHART NOTE CIRCLING NA S OF RWYS 5 AND 30. THIS IS RNAV (GPS) RWY 30, AMDT 1C. 1910311834-PERM