

**Federal Aviation
Administration**

Transmittal Letter 21-17

June 25, 2021

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
8/12/2021	QM	Midway Atoll	Henderson Fld	1/9732	5/28/2021	NDB RWY 24, Orig-C

12 AUGUST 2021

FDC 1/9732 MDY IAP HENDERSON FLD, MIDWAY ATOLL, QM. NDB RWY 24, ORIG-C... S-24
ALL CATS HAT 553. CIRCLING CAT A/B/C HAA 548, CAT D HAA 568. CHART TDZE 7.
CHART AIRPORT ELEVATION 12. THIS IS NDB RWY 24, ORIG-D. 2105202007-PERM