

**Federal Aviation  
Administration**

**Transmittal Letter 25-14**

**May 9, 2025**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,  
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
6/12/2025	SC	Columbia	Columbia Metro	5/5969	4/15/2025	ILS OR LOC RWY 5, Amdt 3

**AIRAC Date: 12 JUNE 2025**

FDC 5/5969 CAE IAP COLUMBIA METRO, COLUMBIA, SC. ILS OR LOC RWY 5, AMDT 3...  
DELETE NOTE: INOPERATIVE TABLE DOES NOT APPLY TO S-ILS 05 CATS A/B/C/D, S-LOC  
05 CATS A/B AND IKUPY MINIMUMS S-LOC 05 CATS A/B. THIS IS ILS OR LOC RWY 5,  
AMDT 3A. 2504170905-PERM