

**Federal Aviation
Administration**

Transmittal Letter 22-19

July 22, 2022

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
9/8/2022	ME	Sanford	Sanford Seacoast Rgnl	2/8970	5/23/2022	VOR RWY 25, Amdt 14C

AIRAC Date: 9 SEPTEMBER 2022

FDC 2/8970 SFM IAP SANFORD SEACOAST RGNL, SANFORD, ME. VOR RWY 25, AMDT 14C... DELETE
NOTE: RWY 32 HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NA. THIS IS VOR RWY 25, AMDT 14D.
2205041633-PERM