

**Federal Aviation
Administration**

Transmittal Letter 20-03

December 13, 2019

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
1/30/2020	CO	Monte Vista	Monte Vista Muni	9/6133	11/20/2019	VOR/DME-A, Amdt 3

AIRAC Date: 30 JANUARY 2020

FDC 9/6133 MVI IAP MONTE VISTA MUNI, Monte Vista, CO. VOR/DME-A, AMDT 3...
CHART CIRCLING ICON. CIRCLING MDA CAT A 8080/HAA 469, CAT C
8180/HAA/569, CAT D 8360/HAA 749. CIRCLING CAT D VIS 2 1/2. DELETE NOTE
CIRCLING TO RWY 10-28 AND RWY 16-34 NA, CHART NOTE CIRCLING NA TO
RWYS 10, 28, 16 AND 34. THIS IS VOR/DME-A, AMDT 3A. 1911011631-PERM