

**Federal Aviation  
Administration**

**Transmittal Letter 20-12**

**April 17, 2020**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,  
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
5/21/2020	FL	Orlando	Orlando Intl	0/2148	4/2/2020	VOR/DME RWY 18R, Amdt 5E

**AIRAC Date: 21 MAY 2020**

FDC 0/2148 MCO IAP ORLANDO INTL, ORLANDO, FL. VOR/DME RWY 18R, AMDT  
5E... CHART CIRCLING ICON. THIS IS VOR/DME RWY 18R, AMDT 5F.  
2003031530-PERM